

LIST OF PLATES

<u>Serial Number</u>	<u>Plate</u>	<u>Description</u>	<u>Page</u>
1	I.1	Panoramic view, showing terrain characteristics in the central part of the Heran basin (Loc. Around Lalpur)	6
2	II.1	Angular unconformity between Bagh sandstone and Champani metamorphics (Loc. Near Ghantoli railway bridge)	32
3	II.2	Exposures of the Precambrian quartzites and gneisses (Loc. Near Songir Fort)	32
4	II.3	Exposures of phyllite striking across the river and the section of the alluvial deposits (Loc. Near Vora)	33
5	II.4	Xenolithic patch of the Basement granite within the basaltic flow (Loc. Sodhwad)	33
6	II.5	Interbedded sequence of Bagh sedimentaries: (Loc. Kawant-Karipani road section)	38
7	II.6	Trap overlying Bagh (Loc. Rami reservoir, Khandibaru village)	38
8	II.7	Basaltic dyke in trap flow (Loc. Heran bed near Rangpur)	43
9	II.8	River, terraces along Heran river (Loc. Near village Vora)	43
10	III.1	A prominent fault scarp on the left bank of Heran river (Loc. Heran bridge near Panvad).	60
11	III.2	East-west dislocation of dyke on account of F_1 - F_1 fault (Loc. Heran bed near Rangpur Ashram)	60
12	III.3	Displacement of microdyke in the basaltic flow due to F_1 - F_1 fault (Loc. Rami river bed near Wanta)	61
13	IV.1	A view of the dyke ridge in the trappean upland area (Loc. Near village Rendi).	83

<u>Serial Number</u>	<u>Plate</u>	<u>Description</u>	<u>Page</u>
14	IV.2	A close view of the Heran river terrace. (Loc. Near village Vora).	83
15	IV.3	A prominent dyke, controlling the Kara river flow by giving a 'U' turn. (Loc. Near village Burma and Bhiratha)	91
16	IV.4	A dyke obstacle diverting the Kara river flow. The other side of the dyke, alluvium pocket are seen. (Loc. Near Kawant)	91
17	IV.5	Fluvial terrace deposits along Kara river (Loc. Near Kawant bridge)	92
18	IV.6	Formation of water channels along less competent dykes, due to differential erosion. Presence of Knick point has developed water pool. (Loc. Heran bed between Rangpur Ashram and Jharoi)	98
19	VI.1	Undulatory terrain with surficial depression, provides an adequate site for the development of phreatic aquifers. (Loc. village Pipaldi)	139
20	VII.1	Columnar joints in basalt, facilitating high rate of infiltration to recharge the phreatic aquifers. (Loc. Near Karipani)	185
21	VII.2	Joint pattern in Bagh sandstone. (Loc. Songirhill quarries)	185
22	VII.3	Residual trappean topography characterising scanty vegetation and poor groundwater potential. (Loc. Near village Bhiratha)	189
23	VII.4	A view of typical waste land terrain of Bagh sandstone with poor groundwater occurrence. (Loc. Near village Wandmala)	189

<u>Serial Number</u>	<u>Plate</u>	<u>Description</u>	<u>Page</u>
24	VII.5	Wide open river bed with gently rising northern bank. Dry sandy cover seen in the middle part over the sub-surface river flow. (Loc. Near village Mugalwant)	190
25	VII.6	Local depression in the basaltic terrain with moderate groundwater potential, characterised by thick vegetation growth. (Loc. Near village Rumadia)	192
26	VII.7	A view of a typical low lying trappean landscape with of phreatic aquifers with thick residual soil cover. (Loc. Area north of Dungargam)	193
27	VII.8	Pediments of basaltic hill, a zone of high groundwater potential. Rich agriculture land is seen in the photograph. (Loc. village Rundhi)	195
28	VII.9	River terrace; presence of heterogenous material has produce potential zone of groundwater occurrence. (Loc. Near village Moradungar)	195
29	VII.10	An upstream view of check dam, enhancing the groundwater yield of the nearby well. (Loc. Near Panvad)	196
30	VII.11	A check dam for augmenting local ground water potential. (Loc. Near village Untvali)	196
31	VII.12	Embankment across a depression in trappean terrain. Groundwater recharge is locally enriched by the water pool. (Loc. village Dungargam)	197
32	VII.13	A road embankment creating surface water pool and indirectly enhancing the rate of infiltration for recharging the phreatic aquifers of metamorphics. (Loc. village Nandpur)	197
33	VIII.1	Downstream and upstream views of the fluorite mine tailwater settling tank. (Loc. Raisingpur)	244

<u>Serial Number</u>	<u>Plate</u>	<u>Description</u>	<u>Page</u>
34	VIII.2	Narmada water is being supplied through pipeline, to the inhabitants residing in the vicinity of Ambadongar fluorite mine, Karipani. (Loc. village Bujetha)	246
35	VIII.3	Check dam providing potential recharge site to the aquifers in granitic terrain, ensure perennial supply for domestic and agriculture purposes. (Loc. Near Panvad)	247