

List of Figures

- 2.1 A Perfect 50Hz signal in both time and frequency domains
- 2.2 Typical frequency spectra of a good motor
- 2.3 Problems, failures and possible online monitoring Technique for Induction motors
- 3.1 Different faults within Induction motors
- 3.2 Rotor bar current distribution before fault
- 3.3 Rotor bar current distribution after fault
- 3.4 Comparison of air gap flux spectra for single broken bar and various asymmetries in the same motor
- 3.5 Oscillogram with no rotor failure
- 3.6 Oscillogram with one bar failure
- 3.7 Oscillogram with two bars failure
- 3.8 Oscillogram with three bars failure
- 3.9 Types of Rolling element bearing Misalignments
- 3.10 Ball Bearing Dimensions
- 3.11 Flowchart showing the effects of two categories of faults and where their signature appear.
- 3.12 Peaks at characteristic frequencies for bearing faults
- 3.13 Air gap Eccentricity

- 3.14 Static and Dynamic Eccentricity
- 3.15 Current Spectrum with inherent level of eccentricity
- 3.16 Current spectrum with eccentricity fault.
- 3.17 Schematic Diagram of Laboratory Machine
- 3.18 Variation of 398Hz component
- 3.19 Variation of 498 Hz Component
- 5.1 Hardware Scheme
- 7.1 Current Signature W/o rotor Fault
- 7.2 Current Signature with rotor fault
- 7.3 Current Signature without Eccentricity Fault
- 7.4 Current Signature with Eccentricity fault
- 7.5 Current Signature without Stator Fault
- 7.7 Current Signature with stator Fault
- 7.8 Current Signature with bearing faults
- 7.9 Current Signature with Misalignment
- 7.10 Current Signature with Torque Pulsations
- 7.11 Current Signature with Misalignment at field
- 7.12 Current Signature with rotor fault at field